## **NOTICE**

All drawings located at the end of the document.

Buffer Zone Sampling and Analysis Plan FY04 Addendum #BZ-04-11 IHSS Group 900-11, PAC SE-1602 (East Firing Range)

January 2004



20

Buffer Zone Sampling and Analysis Plan FY04 Addendum #BZ-04-11 IHSS Group 900-11, PAC SE-1602 (East Firing Range)

Approval received from the U S Environmental Protection Agency, Region VIII

January 14, 2004

Approval letter contained in the Administrative Record

January 2004

#### TABLE OF CONTENTS

| 10      | INTRODUCTION   | 1       |
|---------|--|---------|
| 20      | EXISTING CHARACTERIZATION INFORMATION  | 1       |
| 3 0     | SAMPLING   | 4       |
| 4 0     | REFERENCES .   | 16      |
|         | LIST OF TABLES   |         |
| Table 1 | PCOCs for PAC SE-1602  | 4       |
| Table 2 | Approximate Number of Soil Samples to be Collected and Analyzed Using Laboratory Method 6010 Based on XRF Sampling Locations and Results | 10      |
| Table 3 | PAC SE-1602 Sampling and Analysis Summary  | 10      |
| Table 4 | Sampling Specifications for PAC SE-1602 .  | 11      |
|         | LIST OF FIGURES  |         |
| Figure  | 1 IHSS Group 900-11, PAC SE-1602 General Location  | 2       |
| Figure  | 2 IHSS Group 900-11, PAC SE-1602 Existing Sampling Data  | 3       |
| Figure  | 3 Bullet Trajectories Used to Identify Firing Range Impact Zones and Samplin Locations   | ng<br>5 |
| Figure  | 4 IHSS Group 900-11, PAC SE-1602 Proposed Sampling Locations Near Southern Targets   | 6       |
| Figure  | 5 IHSS Group 900-11, PAC SE-1602 Proposed Sampling Locations Near<br>Northern Targets  | 8       |
| Figure  | 6 PAC SE-1602 Proposed Background Sampling Locations   | 9       |

#### **ACRONYMS AND ABBREVIATIONS**

AL action level BZ Buffer Zone

BZSAP Buffer Zone Sampling and Analysis Plan

DOE US Department of Energy ER Environmental Restoration

FY Fiscal Year

HRR Historical Release Report

IHSS Individual Hazardous Substance Site

mg/kg milligram per kilogram
PAC Potential Area of Concern

pC1/g picocuries per gram

PCOC potential contaminant of concern RFCA Rocky Flats Cleanup Agreement SAP Sampling and Analysis Plan UBC Under Building Contamination

WRW wildlife refuge worker XRF x-ray fluorescence

#### 1.0 INTRODUCTION

This Buffer Zone (BZ) Sampling and Analysis Plan (SAP) (BZSAP) Addendum #BZ-04-11 includes Individual Hazardous Substance Site (IHSS) Group-specific information, sampling locations, and potential contaminants of concern (PCOCs) for IHSSs and Potential Areas of Concern (PACs) proposed for characterization during Fiscal Year (FY) 04 This BZSAP Addendum is a supplement to the BZSAP (DOE 2002) and includes data and proposed sampling locations for PAC SE-1602, which is part of IHSS Group 900-11 IHSS Group 900-11 also contains IHSS 112 (903 Pad), IHSS 140 (Hazardous Disposal Area), and IHSS 155 (903 Lip Area), however, these IHSSs are not addressed in this Addendum The location of PAC SE-1602 (East Firing Range) is shown on Figure 1

#### 2.0 EXISTING CHARACTERIZATION INFORMATION

PAC SE-1602 consists of a pistol range, northern targets, and southern targets, as shown on Figure 2. The pistol range consists of an asphalt-paved parking area, a small arms firing range with a berm, and the remnants of at least three machine-gun mounts. The mounts were used to fire at downhill targets. The northern targets currently consist of two rows. One row is located 50 yards from the pistol range and is approximately 185 feet long. The other row is located 100 yards from the pistol range and is approximately 100 feet long. The southern targets consist of one row approximately 75 feet long.

Infrastructure within the pistol range will be removed as an Environmental Restoration (ER) action in accordance with an ER Rocky Flats Cleanup Agreement (RFCA) Decision Document The Decision Document will also include any soil removals based on the implementation of this BZSAP Addendum or further characterization efforts

Existing information and data for the PAC and surrounding area are available in Appendix C of the BZSAP (DOE 2002) and the Historical Release Reports (HRRs) for the Rocky Flats Plant (DOE 1992-2003) PCOCs for PAC SE-1602 are presented in Table 1 Contaminant concentrations in soil greater than background means plus two standard deviations are presented on Figure 2 The figure shows that most contaminant concentrations are below RFCA action levels (ALs) (DOE et al 2003) However, two sampling locations, between the northern and southern targets, contained plutonium-239/240 activities in surface soil above the wildlife refuge worker (WRW) AL This contamination will be evaluated in the 903 Lip Area Interim Measure/Interim Remedial Action decision document and removed if necessary One sampling location, south of the southern target, contained a lead concentration in surface soil above the ecological receptor AL This exceedance will be addressed in the closeout or data summary report for PAC SE-1602

### Table 1 PCOCs for PAC SE-1602

| IHSS Group | IHSS/PAC/UBC Site | PCOCs             | Media                       | Data Source   | Sampling Method |
|------------|-------------------|-------------------|-----------------------------|---|-----------------|
| 900-11     | PAC SE-1602       | Metals<br>Uranium | Surface and subsurface soil | HRRs (DOE 1992-2003),<br>process knowledge, and<br>existing sample data | Biased          |

#### 3.0 SAMPLING

Bullets fired from the pistol range toward the northern and southern targets penetrated the individual targets and impinged into the upward-sloping hillside south of Woman Creek Based on bullet trajectories and topography, the greatest number of bullets shot at the northern targets most likely impinged just in front of the southern targets, and the greatest number of bullets shot at the southern targets most likely impinged just behind the southern targets. Figure 3 shows the most probable bullet trajectories and the related impact zone (a little less than 1,000 feet wide). Trajectories from shooting at both the northern and southern targets cover a zone (approximately 100 feet wide) that probably contains some of the highest numbers of bullet impingements, and therefore, probably contains some of the highest concentrations of metals, including lead and possibly depleted uranium

Bullets were also shot at the base of the northern targets (just in front of the first target row) According to Site security personnel, shooters generally started shooting at the base of the individual targets and then moved their trajectories up into the targets. This initial shooting created a visible depression in the ground. This ground depression and the area behind it could also contain some of the highest numbers of impingements, and therefore, some of the highest metal concentrations.

This BZSAP Addendum proposes to evaluate the areas most impacted by the East Firing Range operations. The sampling objective is to determine whether metal contamination is present in the areas most impacted, not to fully characterize the PAC. Sampling will occur in areas where the highest metal concentrations are expected. Results will be used to determine whether detected concentrations are of concern, define further characterization needs, and/or make remediation decisions. If metal concentrations in the most impacted areas are low, it is assumed that metal concentrations in other areas impacted by the East Firing Range would also be low or undetectable.

Most samples will be collected from the zone impacted by shooting at both the northern and southern targets (associated with the red trajectories shown on Figure 3) Twenty-five sampling locations are proposed within this zone, based on five trajectories spaced approximately 25 feet apart at the southern boundary of the PAC and five locations per trajectory. The five locations along each trajectory are situated on five 5-foot contour lines (Figure 4) Fewer samples will be collected from both sides of this zone.

Locations for these samples are based on 10 trajectories, spaced approximately 75 feet apart, and three locations per trajectory (i.e., on the three contours) (Figure 4) Sampling on the contours within the impact zone will allow a vertical evaluation of bullet distribution and metal concentrations

Fifteen sampling locations are also proposed around the first row of the northern targets, in an area 15 feet wide and 20 feet long (Figure 5) The area covers 10 feet in front of the first row of targets (where the bullet depression is) and ten feet behind the first row

Two samples will be collected from each sampling location, from 0 to 0 5 foot and 0 5 to 2 5 feet. Hand tools, such as Shelby tubes, will be used to minimize impacts to the Preble's meadow jumping mouse habitat. Each sample will be analyzed using a field x-ray fluorescence (XRF) instrument. Prior to analysis, each sample will be sieved to obtain a homogeneous sample and remove bullets, fragments, and other debris. The type and volume of debris removed will be recorded by sampling location and depth interval. Debris may also be analyzed for waste management purposes. All sampling locations will be surveyed and flagged. To minimize the impact to the Preble's meadow jumping mice, sampling may be conducted during their hibernation season (October 1 to May 15).

Background samples will also be collected Four background sampling locations will be selected south of the East Firing Range along and upgradient of the dirt road (Figure 6) Two samples will be collected from each location, at 0 to 0 5 foot and 0 5 to 2 5 feet

XRF (Method 6200) results will be verified using Laboratory Method 6010 Soil samples will be collected from 16 locations within the three impact zones and where background samples were collected, adjacent to the locations sampled and analyzed using Method 6200, as summarized below in Table 2 Five samples will be collected from the intervals with the highest concentrations, six samples will be collected from the intervals with concentrations closest to the AL, and five samples will be collected from the intervals with the lowest concentrations (measured using Method 6200) These 16 additional samples that will be analyzed using Method 6010 represent more than 10% of the original samples that will be analyzed using Method 6200 (16 Method 6010 analyses divided by 148 Method 6200 analyses equals 10 8%)

The proposed sampling and analysis specifications for PAC SE-1602 are summarized in Table 3, and listed by sampling location in Table 4. The proposed sampling locations are the starting point for characterization of PAC SE-1602. They will be field-located using survey equipment to accurately establish trajectories and walkdowns to find the areas most impacted by bullet fire. The locations will be adjusted through the consultative process. After characterization starts, the number of samples and sampling locations may change based on field conditions and sample results. If contaminant concentrations are found to be high, additional samples may be collected in consultation with the regulatory agencies, and a contact record will be issued.

Table 2
Approximate Number of Soil Samples to be Collected and Analyzed Using Laboratory Method 6010 Based on XRF Sampling Locations and Results

| XRF Sampling Area   |         | Total Number of Samples |        |    |
|---|---------|-------------------------|--------|----|
|   | Highest | Closet to AL            | Lowest |    |
| Northern Target Area  | 1       | 1                       | 1      | 3  |
| Southern Target Area impacted from shooting at both the northern and southern targets | 3       | 3                       | 3      | 9  |
| Southern Target Area impacted from shooting at the northern targets                   | 1       | 1                       | 1      | 3  |
| Background  | 0       | 1                       | 0      | 1  |
| Total Number of Samples   | 5       | 6                       | 5      | 16 |

Table 3
PAC SE-1602 Sampling and Analysis Summary

| Category                               | Total |
|--|-------|
| Number of Sampling Locations           | 74    |
| Number of Samples                      | 164   |
| Number of Metal Analyses (Method 6200) | 148   |
| Number of Metal Analyses (Method 6010) | 16    |

Table 4
Sampling Specifications for PAC SE-1602

| Location | Location Easting Northing Media Depth Analyte On-Site |            |                 |                     |           |                 |  |  |  |  |  |  |
|----------|---|------------|-----------------|---------------------|-----------|-----------------|--|--|--|--|--|--|
| Location | . rasimg  | 1407       | '' tátema       | Interval<br>(feet.) | Emaily to | Field<br>Method |  |  |  |  |  |  |
|          | Locations Around the Southern Targets                 |            |                 |                     |           |                 |  |  |  |  |  |  |
| CV31-002 | 2087029 440   | 747702 272 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV31-002 | 2087029 440   | 747702 272 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV31-003 | 2087114 943   | 747711 821 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV31-003 | 2087114 943   | 747711 821 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV32-002 | 2087032 478   | 747849 407 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV32-002 | 2087032 478   | 747849 407 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV32-003 | 2087031 176   | 747779 529 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV32-003 | 2087031 176   | 747779 529 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV32-004 | 2087107 131   | 747848 539 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV32-004 | 2087107 131   | 747848 539 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV32-005 | 2087111 905   | 747764 772 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CV32-005 | 2087111 905   | 747764 772 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW31-007 | 2087200 013   | 747720 935 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW31-007 | 2087200 013   | 747720 935 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW31-008 | 2087292 027   | 747712 689 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW31-008 | 2087292 027   | 747712 689 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW32-002 | 2087182 218   | 747849 407 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW32-002 | 2087182 218   | 747849 407 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW32-003 | 2087191 332   | 747783 001 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW32-003 | 2087191 332   | 747783 001 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW32-004 | 2087266 419   | 747821 630 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW32-004 | 2087266 419   | 747821 630 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW32-005 | 2087280 308   | 747763 036 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |
| CW32-005 | 2087280 308   | 747763 036 | Subsurface soil | 0 5-2 5             | Metals    | 6200            |  |  |  |  |  |  |
| CX31-031 | 2087354 527   | 747741 334 | Surface soil    | 0 0-0 5             | Metals    | 6200            |  |  |  |  |  |  |

| Location | Easting     | Northing   | Media           | Depth<br>Interval<br>(feet.) | - Analyte | On-Site<br>Field<br>Method |
|----------|-------------|------------|-----------------|------------------------------|-----------|----------------------------|
| CX31-031 | 2087354 527 | 747741 334 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-032 | 2087363 207 | 747712 689 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-032 | 2087363 207 | 747712 689 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-033 | 2087373 624 | 747676 230 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-033 | 2087373 624 | 747676 230 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-035 | 2087385 343 | 747638 036 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-035 | 2087385 343 | 747638 036 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-036 | 2087371 454 | 747761 300 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-036 | 2087371 454 | 747761 300 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-037 | 2087379 700 | 747736 994 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-037 | 2087379 700 | 747736 994 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-038 | 2087387 947 | 747710 518 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-038 | 2087387 947 | 747710 518 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-039 | 2087398 797 | 747676 230 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-039 | 2087398 797 | 747676 230 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-040 | 2087411 384 | 747639 772 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-040 | 2087411 384 | 747639 772 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-041 | 2087396 193 | 747756 525 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-041 | 2087396 193 | 747756 525 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-042 | 2087403 138 | 747734 824 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-042 | 2087403 138 | 747734 824 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-043 | 2087412 252 | 747710 953 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-043 | 2087412 252 | 747710 953 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-044 | 2087422 669 | 747678 400 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-044 | 2087422 669 | 747678 400 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-045 | 2087435 690 | 747641 508 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |
| CX31-045 | 2087435 690 | 747641 508 | Subsurface soil | 0 5-2 5                      | Metals    | 6200                       |
| CX31-046 | 2087419 197 | 747754 789 | Surface soil    | 0 0-0 5                      | Metals    | 6200                       |

| Location | Easting.    | Northing   | Media           | Depth<br>Interval<br>(feet.) | Analyte | On-Site<br>Field<br>Method |
|----------|-------------|------------|-----------------|------------------------------|---------|----------------------------|
| CX31-046 | 2087419 197 | 747754 789 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-047 | 2087427 009 | 747733 956 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-047 | 2087427 009 | 747733 956 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-048 | 2087434 822 | 747711 821 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-048 | 2087434 822 | 747711 821 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-049 | 2087446 107 | 747681 439 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-049 | 2087446 107 | 747681 439 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-050 | 2087460 429 | 747642 810 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-050 | 2087460 429 | 747642 810 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-051 | 2087442 634 | 747752 619 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-051 | 2087442 634 | 747752 619 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-052 | 2087450 013 | 747733 088 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-052 | 2087450 013 | 747733 088 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-053 | 2087459 127 | 747710 518 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-053 | 2087459 127 | 747710 518 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-054 | 2087471 280 | 747679 268 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-054 | 2087471 280 | 747679 268 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-055 | 2087486 037 | 747641 074 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-055 | 2087486 037 | 747641 074 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-056 | 2087516 853 | 747740 466 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-056 | 2087516 853 | 747740 466 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX31-057 | 2087530 308 | 747712 689 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX31-057 | 2087530 308 | 747712 689 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CX32-000 | 2087345 846 | 747769 546 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CX32-000 | 2087345 846 | 747769 546 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CY31-008 | 2087542 461 | 747685 779 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CY31-008 | 2087542 461 | 747685 779 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CY31-009 | 2087592 374 | 747726 578 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |

| Location | Easting :   | Northing   | Media           | Depth<br>Interval<br>(feet.) | Analyte | On-Site<br>Field<br>Method |
|----------|-------------|------------|-----------------|------------------------------|---------|----------------------------|
| CY31-009 | 2087592 374 | 747726 578 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CY31-010 | 2087607 565 | 747699 234 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CY31-010 | 2087607 565 | 747699 234 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CY31-011 | 2087625 360 | 747665 814 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CY31-011 | 2087625 360 | 747665 814 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CY31-012 | 2087678 311 | 747699 668 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CY31-012 | 2087678 311 | 747699 668 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CY31-013 | 2087690 464 | 747679 268 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CY31-013 | 2087690 464 | 747679 268 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CY31-014 | 2087701 749 | 747660 171 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CY31-014 | 2087701 749 | 747660 171 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CZ31-004 | 2087749 492 | 747710 518 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CZ31-004 | 2087749 492 | 747710 518 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CZ31-005 | 2087763 815 | 747689 685 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CZ31-005 | 2087763 815 | 747689 685 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CZ31-006 | 2087780 742 | 747664 512 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CZ31-006 | 2087780 742 | 747664 512 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CZ31-007 | 2087825 881 | 747720 935 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CZ31-007 | 2087825 881 | 747720 935 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CZ31-008 | 2087843 676 | 747696 630 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CZ31-008 | 2087843 676 | 747696 630 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CZ31-009 | 2087899 232 | 747623 713 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CZ31-009 | 2087899 232 | 747623 713 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| DA31-002 | 2087947 843 | 747676 230 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| DA31-002 | 2087947 843 | 747676 230 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| DA31-003 | 2087991 679 | 747622 845 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| DA31-003 | 2087991 679 | 747622 845 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| DA31-004 | 2088026 836 | 747581 612 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |

| Location | Easting     | Northing   | Media           | Depth<br>Interval<br>(feet.) | Analyte | On-Site<br>Field<br>Method |
|----------|-------------|------------|-----------------|------------------------------|---------|----------------------------|
| DA31-004 | 2088026 836 | 747581 612 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |

Twelve sampling intervals in this area will be re-sampled, and samples will be analyzed off-site using Method 6010 (refer to page 8) Four samples will be collected from the intervals with the highest concentrations, four samples will be collected from the intervals with concentrations closest to the AL, and four samples will be collected from the intervals with the lowest concentrations (measured using Method 6200)

| Locations Around the Northern Targets |             |            |                 |         |        |      |  |  |  |  |
|---------------------------------------|-------------|------------|-----------------|---------|--------|------|--|--|--|--|
| CV35-000                              | 2087111 937 | 748560 260 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV35-000                              | 2087111 937 | 748560 260 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV35-001                              | 2087113 890 | 748555 247 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV35-001                              | 2087113 890 | 748555 247 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV35-002                              | 2087116 039 | 748550 495 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV35-002                              | 2087116 039 | 748550 495 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV35-003                              | 2087120 661 | 748558 307 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV35-003                              | 2087120 661 | 748558 307 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV35-004                              | 2087122 810 | 748553 164 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV35-004                              | 2087122 810 | 748553 164 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV35-005                              | 2087126 911 | 748560 976 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV35-005                              | 2087126 911 | 748560 976 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV35-006                              | 2087128 995 | 748555 898 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV35-006                              | 2087128 995 | 748555 898 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV36-007                              | 2087107 445 | 748570 416 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV36-007                              | 2087107 445 | 748570 416 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV36-008                              | 2087109 594 | 748565 664 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV36-008                              | 2087109 594 | 748565 664 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV36-009                              | 2087114 086 | 748573 151 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV36-009                              | 2087114 086 | 748573 151 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV36-010                              | 2087116 234 | 748568 463 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |
| CV36-010                              | 2087116 234 | 748568 463 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |
| CV36-011                              | 2087118 513 | 748563 125 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |

| Location | Easting     | Northing   | Media           | Depth<br>Interval<br>(feet.) | Analyte | On-Site<br>Field<br>Method |
|----------|-------------|------------|-----------------|------------------------------|---------|----------------------------|
| CV36-011 | 2087118 513 | 748563 125 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CV36-012 | 2087120 401 | 748575 885 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CV36-012 | 2087120 401 | 748575 885 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CV36-013 | 2087122 354 | 748571 328 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CV36-013 | 2087122 354 | 748571 328 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |
| CV36-014 | 2087124 763 | 748565 859 | Surface soil    | 0 0-0 5                      | Metals  | 6200                       |
| CV36-014 | 2087124 763 | 748565 859 | Subsurface soil | 0 5-2 5                      | Metals  | 6200                       |

Three sampling locations in this area will be re-sampled, and samples will be analyzed off-site using Method 6010 (refer to page 8) One sample will be collected from the interval with the highest concentration, one sample will be collected from the interval with concentration closest to the AL, and one sample will be collected from the interval with the lowest concentration (measured using Method 6200)

|          | Background Locations |            |                 |         |        |      |  |  |  |  |  |
|----------|----------------------|------------|-----------------|---------|--------|------|--|--|--|--|--|
| CP29-000 | 2085854 623          | 747300 815 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |  |
| CP29-000 | 2085854 623          | 747300 815 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |  |
| CQ29-000 | 2086032 575          | 747318 176 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |  |
| CQ29-000 | 2086032 575          | 747318 176 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |  |
| CY28-000 | 2087690 561          | 747010 017 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |  |
| CY28-000 | 2087690 561          | 747010 017 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |  |
| CZ28-000 | 2087833 790          | 746962 274 | Surface soil    | 0 0-0 5 | Metals | 6200 |  |  |  |  |  |
| CZ28-000 | 2087833 790          | 746962 274 | Subsurface soil | 0 5-2 5 | Metals | 6200 |  |  |  |  |  |

The background sampling interval with the XRF metal concentration closest to the AL will be resampled (refer to page 8), and the sample will be analyzed off-site using Method 6010


#### 4.0 REFERENCES


DOE, 1992-2003, Historical Release Reports for the Rocky Flats Plant, Golden, Colorado


DOE, 2002, Final Buffer Zone Sampling and Analysis Plan, Rocky Flats Environmental Technology Site, Golden, Colorado, June

DOE, CDPHE, and EPA, 2003, Modifications to the Rocky Flats Cleanup Agreement Attachment 5, Rocky Flats Environmental Technology Site, Golden, Colorado, June












FIGURE 6

IHSS Group 900 11 PAC SE 1602 Proposed Background Sampling Locations

KEY

Trajectories for northern targets Trajectories for northern and southern targets

Proposed background sampling locations

Preble s Meadow Jumping Mouse habitat

5 ft Contour interval


State Plane Coord nate Projection Colorado Central Zone Datum NAD 27

US Department of Energy Rocky Flats Environmental Technology Site

KAISER+HILL

F1 w/p j t /Fy2004/900 11 t g p 500 11p 1602 RADMS

D t 12/16/03



# **Proposed Sampling Locations** Near Southern Targets IHSS Group 900 11 PAC SE 1602 FIGURE 4

KΕΥ


Proposed Sampling Locations PAC SE 1602 Preble s Meadow Jumping Mouse habitat

State Plane Coord nate Projection Colorado Central Zone Datum NAD 27

US Department of Energy Rocky Flats Environmental Technology Site

RADMS

Dat 12/16/03 9



# FIGURE 3

Bullet Trajectories Used To Identify Firing Range Impact Zones and Sampling Locations

# ΚEΥ

Trajectories for northern target Trajectories for both northern and southern targets

Preble s Meadow Jumping v e abitat

Paved road

200 Feet Scale 1 2000

US Department of Energy Rocky Flats Environmental Technology Site

**NAISER•HILI** 27 17 )

RADMS

F1 w/p j 1 /Fy2004/900 11 /g p900 11p 1602 p

D t 12/16/03